si4i0101.zip PVI-486SP3 A4 version chipset BIOS 0101.

si4i0202.zip PVI-486SP3 B2 & B3 chipset BIOS 0202. Note: Not for A4 version chipset.
Please read README.TXT file first.

si4i0203.zip PVI-486SP3 BIOS rev. 0203. Note: 02xx BIOS can only support 497/496 B
version chipset.

       (1) Add Intel DX4 L1 Write-back CPU Support.

       (2) Add IDE Prefetch Item in Chipset feature menu.

       (3) Fix Monochrome No display when used with PCI VGA.

       (4) Update NCR BIOS to 3.07.00.

       (5) Fix Mitsumi CD-ROM NT-Install Failed.

       (6) Fix Qlogic SCSI and Promise IDE Controller Init Failed.

si4i0205.zip PVI-486SP3 BIOS rev. 0205.

       (1) Support Cyrix DX4 CPU.

       (2) Support AMD DX4-120Mhz CPU.

       (3) Support disable on board secondary IDE controller.

si4i0301.zip PVI-486SP3 (SiS 496/497 B version chipset) M/B, Plug and Play BIOS rev.
0301.

       (1) This BIOS do not support A4 version chipset.

       (2) Support Cyrix M1SC/5x86 CPU.

       (3) Support Cyrix DX4 CPU.

       (4) Support AMD DX4-120Mhz CPU.

       (5) PVI-486SP3 M/B only support SST PH29EE010 & Winbond W29EE01 +5V Flash EPROM for
PnP BIOS.

si4i0304.zip PVI-486SP3 (SiS 496/497 B ver. chipset) M/B, Plug and Play BIOS rev. 0304.
12/05/95

       (1) This BIOS do not support A4 version chipset.

       (2) Support AMD X5 (5x86) CPU. (3) Support ESS0968 PnP card.

       (4) Support Cyrix M1sc (5x86) 133Mhz CPU. (5) Support NCR 860.

       (6) Fix Win 95 BatteryMeter present on taskbar.

       (7) Fix 64MB DRAM hang up problem.

       (8) Fix MS mouse driver 9.01 hang up problem when NO mouse attached.

       (9) Fix the floppy R/W problem when install the OPTi chipset PnP sound card.

       (10)Fix Diamond multimedia kit 8000 (OPTi) sound card hang up problem while

installation.

si4i0305.zip PVI-486SP3 (SiS 496/497 B ver. chipset) M/B, Plug and Play BIOS rev. 0305.
04/06/96

>   (1) This BIOS do not support A4 version chipset.

>   (2) Fix Crystal sound card hang with UMC IO.

>   (3) Fix hang on PnP init when warmboot.

>   (4) Fix ICU configuration error if ECP DMA disabled.

si4i0306.zip PVI-486SP3 (SiS 496/497 B ver. chipset) M/B, Plug and Play BIOS rev. 0306.
07/06/96

>   (1).Update to Award BIOS version 4.51PG.

>   (2).Modify Int10 for Mono display.