

GA-P35C-DS3R (rev. 2.0)

[rev. 2.1](#) [rev. 1.x](#)

Intel® P35 + ICH9R Chipset

[Compare](#)

Version	Size	Date	Download	Description
F12	0.73 MB	2009/06/19		1. Support Xpress BIOS Rescue function
F10	0.72 MB	2008/01/04		1. ADD new version super I/O code.
F9	0.72 MB	2007/12/19		1. Fix CPU compatibility issues
F8	0.72 MB	2007/11/15		1. Fix: Some of 1000 GB (1TB) HDDs will be detected size error.
F7	0.72 MB	2007/11/13		1. Fix : Some motherboards do not allow the DDR2 voltage to be increased to 0.4V in a high-temperature environment.
F6	0.71 MB	2007/10/29		1. Support Intel 45nm Yorkfield CPU
F4	0.70 MB	2007/09/07		1. Fix PS2 keyboard compatibility issues
F2	0.71 MB	2007/05/21		1. Enhance DDR3 overclocking ability to 1333MHz or higher
F1	0.69 MB	2007/04/13		1. First Release

Warning:

Because BIOS flashing is potentially risky, if you do not encounter problems using the current version of BIOS, it is recommended that you not flash the BIOS. To flash the BIOS, do it with caution. Inadequate BIOS flashing may result in system malfunction.

Update CPU ID/Micro codes in new BIOS means?