ADVANTAGE SERIAL PORT #2 UPGRADE KIT

The following information is to clarify the locations in which
the upgrade components are to be installed. These components are
supplied with the Serial Port #2 Upgrade Kit (Part #500212-011,
Model #ADV-000S) for the Advantage board.

COMPONENT	LOCATION ON ADVANTAGE BOARD
1489	U72
1488	U80
16450	U73

Note that component 74LS125, which is listed in the Advantage
Option Installation Guide, Section #2 Serial Port, is already
soldered on the board.