Epox EP-8KDA3I BIOS revision history

Date	Ver.	Description
07.09.2006	6907	Fixed • Add use Com Reset for SATA function to solve Maxtor SATA II DiamondMax 10 can't install OS • Solve some KVM can't shutdown. • Support SST49LF004B flash ROM. • Support automatic load awdflash from CD-ROM in bootblock. • After awdflash BIOS under DOS, LAN can't link internet. • Updated: CPU Microcode
02.05.2006	6502	Fixed • Update CPU code support • Support SS49LF004B flash ROM. • Support automatic load awdflash from CD-ROM in bootblock. • Support Turion mobile CPU.
10.10.2005	5b10	Fixed • Solved some USB flash can't boot. • Solved: Cool&Quiet control function select disable but BIOS can't disable Cool&Quiet • Update CPU code. (Turion mobile CPU FID/VID and Cool&Quiet.)
04.10.2005	5a04	Fixed • Solve X.5 ratio of CPU real clock show error. • Support CPU ratio clock funcion can adjust X.5. • Solve Matrox G550 can't install driver. • Update K8 Athlon 754 CPU Ver E6 for Cool'n'Quiet PST table.
15.08.2005	5815	Fixed • Fix K8 754 Athlon 64 2800 CG Rev (ADA2800AEP4AR) after clear CMOS first load default can't boot. • Added DDR433 DDR466 DDR500 support for E version CPU. • Added Thunder Probe support. (EPTP)
02.08.2005	5802	Fixed • Add MCT2 code. • Fix winbond ROM flash fail. • Update DMI mainboard base information. • Support AMD K8 754 Version E6 Sempron 64 CPU.
01.04.2005	5401	Fixed • Hidden over 1.75v options for CPU Voltage item. • Solve Sempron 754 CPU hang POST C1h if DIMM1 & DIMM3 exits. • Add 'Auto' option for HT frequency item. • Add Rev.E CPU code.
05.01.2005	5105	Fixed • Set nVidia LAN PME# wakeup by BIOS control item. • Solve Smart Fan works fail after S3 resume. • Ratio agjustment support x5 ratio. • Set dual double rank memory default 166MHz. • Add Sempron D0 2000Mhz/59W support. • PCB 3.0 support.
23.11.2004	4b23	Fixed • Patch USB device resume fail from S4 mode. • Add auto option for DIMM voltage adjusts item. • Add nVidia LAN boot ROM control item. • Patch WinFlash shows BIOSLock string issue.
22.10.2004	4a22	Fixed • Patch Cool'n'Quiet fail for 8KDA3I 2.0. • Sovle system hang up at POST 01h when adjust CPU ratio, if DIMM2/DIMM3 exists. • Patch USB device compatibility issue. • Patch ACPI shutdown temperaure fail. • Solve some large Hard Disk hang up undeer DOS • Add USB Memory control item.