```
TYAN Tomcat K8S (S2850) V1.00
New features and Fixes :
This is the first release BIOS.

TYAN Tomcat K8S (S2850) V1.01
New features and Fixes :
Add Sil 3114 4-way Raid Support
Enable/Disable option added for Raid
Updated Raid Option Rom

TYAN Tomcat K8S (S2850) V1.03
New features and Fixes :
Add new clock chip support
Updated Sil 3114 Oprom

TYAN Tomcat K8S (S2850) V1.04
New features and Fixes :
Updated Option Rom for SI3114 chip
Fixed Console Redirect Issue
Fixed USB WOL issue
Fixed RTC Wake up state issue
Updated ACPI 2.0 support

TYAN Tomcat K8S (S2850) V1.05
New features and Fixes :
Added DDR 400 support
Added Highpoint 370 RAID support
Added 9600bps for console redirection
Updated Option Rom for Si3114

TYAN Tomcat K8S (S2850) V1.07
New features and Fixes :
Fixed boot without keyboard issue
Updated Silicon Image 3114 firmware to v5.0.31

TYAN Tomcat K8S (S2850) V1.08
New features and Fixes :
Added Opteron CPU CG stepping support
Added Opteron 150 CPU support

TYAN Tomcat K8S (S2850) V1.09
New features and Fixes :
Added AMD D0 and Ex CPU stepping support
Added PXE endless loop function and setup item to fix a int19 issue
Added AMD PowerNOW support
Updated SiL3114 Option ROM to v5.0.48

TYAN Tomcat K8S (S2850) V1.10
New features and Fixes :
Fixed an issue where temperatures were not displaying correctly
Added M2043x Riser card support
Updated SIL3114 firmware to v5.0.49

TYAN Tomcat K8S (S2850) V1.12
New features and Fixes :
Fixed an issue where the FDD isnt usable inside of Windows
Fixed an issue where the CMOS does not load default values after clearing

TYAN Tomcat K8S (S2850) V1.13
New features and Fixes :
Updated Option ROM loading for the BCM5705 LAN Chips
Added an option in the bios to [Enable/Disable] LAN1 or LAN2 in the BIOS setup menu
```