BIOS Revision History

Bios name	Remarks
FB54S009	Date code: 03/03/2003 Checksum: 1000 Initial release.
FB54S00C	Date code: 06/26/2003 Checksum: 1F00 1. Adjust fan setting. 2. Fixed install two different size of DDR , system is not stable. 3. Added HT CPU to show "HT Enable" when BIOS post. 4. Added new display string for DVD+CD-RW devices. 5. Support P4 D1 Core Stepping CPU. (Northwood]
FB54S00D	Date code: 07/16/2003 Checksum: E100 Solved the smart fan miss function when system resume from S3.

Close this window