

# Chaintech CT-9BIA0 BIOS Revision history

|  |
|--|
| Date: 05/27/2002<br>. Add CPU MicroCode for F13<br>. Support Celeron CPU   |
| Date: 10/11/2001<br>. Update Codebase to 09/24/2001<br>. Remove S3 resume Beep (Award for speed up resume from s3 Issue)<br>. Add USB2 Wake Up function  |
| Date: 09/15/2001<br>. Support USB2 Wakeup for M201   |
| Date: 09/13/2001<br>. Fixed system can't wake up from PS2 K/B Mouse under win2000 (if press k/b mouse before enter S1 )  |
| Date: 08/03/01<br>. Fixed some time system can't boot if system has north wood   |
| Date: 07/27/01<br>. Support S1 Wakeup form USB keyboard<br>. Fixed Northwood CPU Ratio Setting error.<br>. Support Intel BrandName<br>. Adjust System Performance  |
| Date: 07/24/01<br>. Add 'Home Key' for Chaintech Style<br>. Change Power on by PCI CARD to Disabled<br>. Change power function to button only  |
| Date: 07/20/01<br>. Fixed AC97 CNR/Modem only(master) detection to be Audio CNR card.<br>. Support PCI IRQ select<br>. Don't Assigned ACPI IRQ to PCI Card<br>. Change Floppy Seek to Disabled<br>. Change Boot sequence to Floppy, CDROM, HDD-0 |
| DATE: 07/02/01<br>. Fixed BIOS setup Feature screen problem<br>. PCI List Add IDE IRQ 14/15<br>. CPU FAN , System Fan Exchange   |
| DATE: 06/29/01<br>. Support Auto Flash (Remove PCI VGA in Boot Block)<br>. Support PS/2 Kb/Mouse wake under win98  |
| DATE: 06/28/01<br>. First release<br>No Ready Issue:<br>. no Auto Flash ( Alt-F2)<br>. can't by Ps2 Key/mouse Resume<br>. Can't Mix SDRAM SPD/noSPD Used   |