

# MS-6309 Lite / v2.x BIOS revision history

<b>Version</b>	Ver 3.8	<b>Update date</b>	2002-03-26
<b>Update Description</b>	Support Maxtor 160GB HDD (4G160J8)		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.7	<b>Update date</b>	2001-09-24
<b>Update Description</b>	-Fixed Celeron 900MHz shown as 933MHz and 950MHz shown as 1GHz -Fixed Intel CPU display that 866Mhz & 933Mhz don't display "B"		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.6	<b>Update date</b>	2001-06-11
<b>Update Description</b>	-Set "PCI Delay Transaction Enable" on BIOS setup -Fix problem wherein system will take long time trying to copy file bigger than 10MB from Panasonic ZIP to HDD under DOS. -Fix problem when Promise ATA-100 IDE card is installed, the BIOS take long time to detect other peripheral devices.		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.5	<b>Update date</b>	2001-04-11
<b>Update Description</b>	-Fixed use UDMA33 CD-ROM with WD HDD cannot install Windows 2000 issue. -Fix sometimes can not adjust CPU ratio issue and update ratio table.		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.4	<b>Update date</b>	2001-02-19
<b>Update Description</b>	-Fixed with WD Caviar 28400 ATA-66 8.4GB HDD compatibility issue. -Fixed DEXIN USB Mouse entry setup to occure system become low speed.		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.3	<b>Update date</b>	2001-01-31
<b>Update Description</b>	-Install WINME with USB Legacy free then USB device can not work. -Under DOS mode run flash utility after return to DOS USB KBD can't work. -1GHz CPU misdisplay to 1MHz. -CPU Host clock 133MHz & SDRAM 133 can't run 3DMark. -CPU 433 misdisplay to 440. -CPU 700 misdisplay to 710. -System can't boot after Install DOS 6.22.		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.2	<b>Update date</b>	2000-12-01
<b>Update Description</b>	-support EON 29f002t and Hyundai 29f002t flash ROM. -fixed system can not enter S4 from S1 or S3 by Power Options icon under W2K or Win98ME		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.1	<b>Update date</b>	2000-11-08
<b>Update Description</b>	-Fixed VT686B IDE timing issue for DMA mode3/2/1. -Support RAID function for Promise 265 chipset. -Can't enter S3 under W2K and resume form S3 under Win98ME by USB device. -Fixed celeron 766MHz misread as 770MHz. -Update code to fixed incorrect HDD information when HDD size > 65GB		
<b>Special note</b>	This BIOS for PCB 2.X Only		

<b>Version</b>	Ver 3.0	<b>Update date</b>	2000-09-06
<b>Update Description</b>	MS-6309Lite AMI BIOS first time release		
<b>Special note</b>	This BIOS for MS-6309 V2.X Only		