

BIOS Revision History

Bios name	Remarks
FT62S00M	Checksum: 4D00 Date:01/12/04 1. Initial release.
FT62S00N	Checksum: C800 Date:01/28/04 1. Add Prescott CPU support.
FT62S00P	Checksum: EC00 Date:02/27/04 1. Fixed connect TV&CRT, signal always out to TV.
FT62S00V	Checksum: 2500 Date:08/31/04 1. Add Celeron D and Prescott E0-Stepping micro code. 2. Fixed system become unstable when install Prescott CPU with Windows XP SP2.
FT62S00X	Checksum: 5F00 Date:10/13/04 1. Fixed smart fan function failed after resume from S3.
FT62S00Z	Checksum: 8700 Date:12/20/04 1. Fixed sometimes detect Fsb(front side bus) irregularly at boot up.
FT62S011	Checksum: D500h Date:12/28/06 1. Fixed sometimes FSB run 166MHz

Close this window