

## QUICK INSTALLATION GUIDE

### Xwave4000 Value PCI Audio Accelerator

#### Driver Installation under Win95 OSR2

1. After you have installed the sound card, restart your Win95 operating system. Insert the driver CD into your CD-ROM drive, assuming your CD-ROM drive is D
2. The "Update Device Driver Wizard" dialog box indicates the "PCI Multimedia Audio Device" has been found. Please click "**Next>**" to continue. Windows will inform you that it was unable to locate the driver, please click "**Other Locations...**".
3. In the "Select Other Location" dialog box, type (or browse to) the driver location "**D:\Xwave4000\Win31\_95\Win95**", and click "**OK**". Windows will inform you that it has found the ALS4000 PCI Audio Device in the specified driver location, please click "**Finish**" to continue.
4. An "Insert Disk" dialog box will appear to ask you insert the driver disk again, click "**OK**". Type (or browse to) the driver location "**D:\Xwave4000\WIN31\_95\Win95**" again and click "**OK**" in the "Copying Files..." dialog box.
5. Windows may ask you to insert the Win95 CD-ROM into your CD-ROM drive, please insert it and click "**OK**" and Windows will copy all the necessary files and complete the driver installation.

#### VxD Driver Installation under Win98

1. After you have installed the sound card, restart your Win98 operating system. Insert the driver CD into your CD-ROM drive, assuming your CD-ROM drive is D.
2. The "Add New Hardware Wizard" dialog box indicates "PCI Multimedia Audio Device" has been found. Please click "**Next**".
3. Select the option "**Search for the best driver for your device (Recommended)**" and click "**Next**".
4. Select "**Specify a location**", type **D:\Xwave4000\Win98vxd** and click "**Next**".
5. Follow the on-screen instructions and you should be able to install the device driver successfully.

#### Application Installation under Win95/98

1. Please insert the driver CD into your CD-ROM drive assuming your CD-ROM drive is D.
2. Click on the START button and select the **RUN** item.
3. Depending on the Operating system and driver you are using, please type the command below in the command line of the RUN dialog box  
For Win95/Win95 OSR2 type **D:\Xwave4000\Win31\_95\Win95\SETUP.exe**  
For Win98 VxD driver type **D:\Xwave4000\Win98vxd\SETUP.exe**  
For Win98 WDM driver type **D:\Xwave4000\Win98\SETUP.exe** and click **OK**
4. During Installation procedures, please select "**Install Applications Only**" in the "Setup Options" dialog box, follow the on screen instructions, you should be able to install the ALSRACK successfully.

For more detailed information on the installation procedures, please refer to the files in your driver CD "D:\Xwave4000\Manual", assuming your CD-ROM drive is D.