

## A8N-SLI PREMIUM BIOS revision history

Version	Date	Description
1303 Beta	2007/07/13	1. Enhance SATA device compatibility
1302 Beta	2006/06/19	1. Latest beta BIOS.
1009	2005/11/04	1. Support new CPUs. Please refer to our website at: <a href="http://support.asus.com/cpusupport/cpusupport.aspx">http://support.asus.com/cpusupport/cpusupport.aspx</a> 2. Fix unstable under 400MHz-Single channel issue. 3. Modify DDR max speed from 400MHz to 333MHz when full loading.
1008	2005/10/07	1. Support showing both Install/Usable Memory size information on POST and SETUP
1007	2005/08/26	1. Support new CPUs. Please refer to our website at: <a href="http://support.asus.com/cpusupport/cpusupport.aspx">http://support.asus.com/cpusupport/cpusupport.aspx</a> 2. Update nVidia onboard Lan PXE ROM to v215.0503
1006	2005/07/26	1. Fixed some Low-RPM CPU fans show 0 RPM in H/W Monitor when Q-fan Enabled 2. Fixed system will hang in memory test 2.09GB if Quick Boot disabled. 3. Change class code of SATA to fit new Driver (WHQL) if RAID is enabled.
1005	2005/06/02	1.Support new CPUs. Please refer to our website at: <a href="http://support.asus.com/cpusupport/cpusupport.aspx">http://support.asus.com/cpusupport/cpusupport.aspx</a> 2.Fixed "ASUS Update" can't update BIOS when using Dual Core CPU. 3.Fixed NOS can't work after enabled NOS by AI-Booster.
1004	2005/05/28	1.Support new CPUs. Please refer to our website at: <a href="http://support.asus.com/cpusupport/cpusupport.aspx">http://support.asus.com/cpusupport/cpusupport.aspx</a> 2.Fixed sometimes system hangs if copying file from USB20 HDD to PATA HDD. 3.Fixed it sometimes fails to enter S3 4.Set DDR voltage default as 2.6V when under full loading 5.Add more DRAM Items in the Bios. 6.Fixed PC Probe cannot run issue when using Dual Core CPU. 7.Removed CHIPSET Fan checking on POST
1003	2005/04/25	1. Support new CPUs. Please refer to our website at: <a href="http://www.asus.com.tw/support/cpusupport/cpusupport.aspx">http://www.asus.com.tw/support/cpusupport/cpusupport.aspx</a> 2. Support CPU Voltage warning message on POST 3. Add Help String for AI-NET. 4. Add AI-Selector Item 5. Modify SETUP String and it's description of DRAM Over 4G remapping function 6. Improve compatibility with some memory modules
1001	2005/02/18	1. First Release BIOS.