

# BIOS Revision History

Bios name	Remarks
FB61S30E	Checksum: 9200 Date: 02/06/2004 Initial release.
FB61S30H	Checksum: 0900 Date: 06/14/2004 1. Update CPU microcode. 2. Add boot up screen for new Celeron CPU.
FB61S30K	Checksum: D700 Date: 08/30/2004 1. Fix CPU Vcore adjustment function. 2. Fix Matrox G550 compatibility issue. 3. Update Prescott E0 setpping microcode.
FB61S30N	Checksum: EF00 Date: 10/28/2004 1. Add Celeron D OSB logo.
FB61S30S	Checksum: 8500 Date: 05/25/2005 1. Add alarm item help string. 2. Add Shuttle XPC full logo. 3. Fixed S3 function fail when use USB device.

Close this window