

BIOS Revision History

Bios name	Remarks
FS56S01F	Checksum: 2800 Initial release 2003/11/12
FS56S01H	Checksum: 2800 Fixed memory initial error. 2003/12/17
FS56S01M	Checksum:DC00 Patch Compatibility Problem With Samsung DDR400 2004/05/05
FS56S01Q	Checksum:7300 Improve DDR compatibility 2004/06/03
FS56S01S	Checksum:1E00 1. Update product message for driver autorun. 2006/01/09
FS56S01T	Checksum:BC04 1. Update VGA BIOS to support wide screen. 2006/05/30

Close this window